






## Fiat Grande Punto

RATING	SCORE	Front: 13.6	Side: 16	Seatbelt reminder: 2	Pole: 2
 <b>ADULT OCCUPANT</b> ★ ★ ★ ★ ★	<b>33</b>				
 <b>CHILD OCCUPANT</b> ★ ★ ★ ☆ ☆	<b>35</b>				
 <b>PEDESTRIAN</b> ★ ★ ★ ☆	<b>19</b>				

### Adult occupant protection



Frontal impact driver



Frontal impact passenger



Side impact driver

Green	GOOD
Yellow	ADEQUATE
Orange	MARGINAL
Brown	WEAK
Red	POOR

### Child restraints

**18 month old Child** Britax-Römer Duo Plus ISOFIX, forward facing

**3 year old Child** Britax-Römer Duo Plus ISOFIX, forward facing

### Pedestrian protection



Pedestrian protection

Green	GOOD
Yellow	ADEQUATE
Red	MARGINAL

### Safety equipment

Front seatbelt pretensioners	<input checked="" type="checkbox"/>
Front seatbelt load limiters	<input checked="" type="checkbox"/>
Driver frontal airbag	<input checked="" type="checkbox"/>
Front passenger frontal airbag	<input checked="" type="checkbox"/>
Side body airbags	<input checked="" type="checkbox"/>
Side head airbags	<input checked="" type="checkbox"/>
Driver knee airbag	<input type="checkbox"/>
ISOfix front	<input type="checkbox"/>
ISOfix rear	<input checked="" type="checkbox"/>

### Car details

Body type	3 door hatchback
Year of publication	2005
Kerb weight	1076kg
VIN from which rating applies	Applies to all Puntos

### Comments

#### Front impact

Structures in the knee-impact area represented potential hazards to the knee and femur protection on the driver's side.

#### Side impact

The head-protecting curtain airbag interacted with the B-pillar trim in the side impact although it deployed correctly in the pole test. Fiat is addressing the issue.

#### Child occupant

The presence of ISOFIX anchorages in the rear outboard seats was not sufficiently well indicated.